


Gila River Wetlands Ecosystem Restoration



Results




Salt Cedar (Pre fire)



Ethan Fire 2008



Salt Cedar After Fire



3 Acre Site

13 Acre Site

Challenges



**Saltcedar
Resprout
Maintenance**


Water and Soil Salinity



- Honey, Velvet and Screwbean Mesquite
- Four Wing Saltbrush
- Native Salt Grass and Alkalai Sacaton
- Pickle Weed
- Hardstem Bulrush
- Wolfberry
- Cottonwood
- Willow

Installing New Native Plants

Irrigation System



**Salt Cedar
Removal**

Department of Environmental Quality
Water Quality Section

